



## **Town of Yorktown**

9800 W Smith St • PO Box 518

Yorktown, IN47396

765-759-4003p • 765-759-4016f

[www.yorktownindiana.org](http://www.yorktownindiana.org)

9/18/2017

The Town has been experiencing some flooding issues in the neighborhoods on the south side of SR 32 along Lindell Dr/York Rd. Tim Caldwell contacted Fluid Waste Services to come out and do a video inspection to determine the cause of the problem. The inspection showed a collapsed storm sewer pipe located underneath SR 32. The collapse of this pipe is causing excess rainwater to back up into these neighborhoods.

INDOT has informed us that we are responsible for the repair of the pipe. As such, I have been procuring bids from local excavating firms to replace the pipe. Watson's Excavating has come in with the lowest bid and their proposal is attached. Watson's has indicated that they will be able to begin the project in the next few days.

Todd Blevins