

Mishawaka, IN / 574.254.9050 Westfield, IN / 317.896.2987 Ionia, MI / 616.527.0050 Fenton, MI / 810.215.1295 Lombard, IL / 630.708.3212 Boulder, CO / 574.286.0765 Littleton, CO / 303.968.7920

March 9, 2023

Mr. Wayne Studebaker Town of Yorktown PO Box 518 Yorktown, IN 47396-0518

Emailed to: wstudebaker@yorktownindiana.org

**RE: WELL CLEANING & PUMP REPLANCEMENT – Well 4** 

Dear Wayne:

Peerless-Midwest, Inc. (PMI) is pleased to provide the following pricing for cleaning and pump rebuild with column replacement for Well #4.

## **WELL 4- REHABILITATION & CLEANING**

This will require a 2-man crew with a service truck and crane to set new pump reset the new one. After pulling the pump, it will be taken to our shop and disassembled and inspected. We will provide a detailed pump teardown report with recommendations.

We recommend we use our double disc surge block cleaning method with extended contact time and additional water and chemicals to remove the iron build up in the well water fractures. This method is the same one-week approach we performed on similar wells in the past several years that have increased each wells' specific capacity. The chemicals we will utilize for this cleaning include sodium hypochlorite, hydrochloric acid, and Aqua Clear. These chemicals will be neutralized before being pumped to a designated location onto the ground. Video inspection of the well casing and screen after cleaning, you will receive a thumb drive copy once processed.

Once we have the post-clean flow test results, we will have a true idea of the improvement of the well.

The estimated total for the well rehabilitation is \$17,280.

## Well 4- Pumping Equipment:

This scope of work would require a 2-man crew with a service truck and crane to complete this work. We have inspected the pump and pipe on site with you after pulling the pump, it was taken to our shop and disassembled and inspected. We recommend a typical replacement and rebuild would include the following: rebuild the stuffing box with a new bearing, new packing, all new 8" threaded steel column pipe, recondition/paint the discharge head, pump rebuild with new stainless-steel bowl shaft, new stainless head shaft, and standard 75 HP VHS motor rebuild.

We will clean and replace the column pipe, make a new motor shaft, check shaft straightness, new stainless steel 1" line shafting, new SS couplings, adjusting nut, spider bearings in pump setting, new pump bowl bearings, machine wear rings, and new pressure gauge, ¾" poly, and airline. We will flow test and pull 2 water samples before putting it back online. All shop and machine shop labor are included in this cost. Total pump project would be \$27,230.

Should you have any questions concerning this information, or if I may be of any further assistance, please feel free to contact me at the office – (317) 896-2987, on my cell – (765) 438-4208, or via email.

Sincerely,

PEERLESS-MIDWEST, INC.

Nick Rice

**Project Manager** 

## **TERMS & ACCEPTANCE**

As a benefit to you, Peerless-Midwest, Inc. (PMI) has developed the ideas and concepts and special techniques detailed in this proposal/quotation. These are considered by PMI to be confidential and proprietary and remain the sole property of PMI. They shall not be used in any way or manner detrimental to the interests of PMI.

The **Town of Yorktown** and its agents and representatives, acknowledge and agree to honor our proprietary right to the contents of this proposal/quotation and refrain from disclosing such content or any information to any third party, without the prior written consent of PMI. Any unauthorized use of these ideas and concepts is strictly prohibited.

## **TERMS**

All pricing is based upon acceptance within 30 days of this date and may be modified if not accepted within 30 days. Quoted prices do not include Indiana sales tax on materials, which will be itemized separately from labor and service when the work is billed.

Terms are net, not subject to discount, and invoices are to be paid in full without retainage within 30 days of presentation. All invoices not paid within 30 days will be subject to 2% per month service and handling fees, plus any court and/or attorney fees required for collection.

ACCEPTED this day of	_, 2021.	
Ву:	For:	Town of Yorktown
Printed Name:	Title:	

QUOTE-Well 1 & Well 2 Cleanings.
WELL 4 CLEANING + PLAN REPLACEMENT