



Yorktown Downtown Improvements Town of Yorktown, Indiana - August 2014






























































- 1 Slateface Concrete Paver
- 2 Asphalt Paver
- 3 Cast-in-Place Concrete
- 4 Pressed Concrete Paver

- 5 ADA Domed Paver
- 6 Duratherm
- 7 Bollard
- 8 Medallion

- 9 Plant Bed
- 10 Pedestrian/Bike Signal
- 11 Stop Sign
- 12 Thermoplastic

- 13 Plant Bed Rail
- 14 Trail Light Fixtures
- 15 Audible Signal Push Button























Yorktown Downtown Improvements East Gateway - August 2014

